

The contact at Anderson Glass Grand Rapids is:
Derrick Stanley 218 326 0331

Suggested Contractors:

Peterson Contracting
Jeff Peterson 218 259 2042

Columbus Exteriors, Inc
Pete King 612 363 7770

Specifications:

Windows:

Anderson Series 400
Unit, Terratone/Clear Pine, High Performance SmartSun Low E4 Glass
Insect Screen, Stone
Extension Jambs, Head and Sill, Clear Pine 5 ¼" Distributor Applied
Hardware Pack, PSC , Anderson Classic Series – Stone

Front Door (without side sidelite)

3' x 6' 8" HDG-B106-010 Select Steel Door – Clear Glass w/Internal Blind
2 ¾" Backset- Double Bore 2 1/8" Bore w/ Strike Prep ANS 9206 (1" x 2 ¼" Standard)
Set of 2D Satin Brass Hinges
Terratone Aluminum Clad Frame w/Unfinished Rabbet Interior -5 ¼" Jamb w/Crown
Line Exterior Trim (Applied)
Compression Weatherstrip
Adjustable – Mill Finished Sill

Front Door with SideLite (Building 11 only)

(same description as above)
Single Sidelite 12" Wide HDS-B129-010 Select Steel-Clear Glass w/Internal Blind

Storm Door

Anderson, Ventilating, Contemporary Dual Vent Full Lite with TruScene with Nickel
Hardware, 36" x 80" Terratone

Patio Door

PS8
Unit, Terratone/PI Terratone, Low E SmartSun Tempered Glass
Insect Screen, Gliding, Terratone
Extension Jamb, Head Member, Interior, Clear Pine, 5 ¼"
Extension Jambs, Side Members, Interior, Clear Pine, 5 ¼"
Hardware Trim Set, GD, 2 Panel, Tribeca-Stone
FWG/PS/NL – Labor for Two-panel frame assembly –A/W Non- Factory Directed
Adjustment Comment: FWG/PS/SWL- Labor for Two-panel frame assembly- A/W Non
Factory Direct Item Sizes, Costs and Labor Costs will be provided by your Contractor.

Desired Left or Right Opening Doors and in some cases Windows should be discussed with your contractor before ordering.

Egress requirements, especially on buildings 1,2, and 3 need to be adhered to by window type and wall location. Also Loft windows need to be large enough and open correctly to meet this requirement. Loft windows should be ordered with a straight arm to ensure clear opening is adequate. The contractors should be familiar with this ordinance but the owner should remind them. Owners will pay the contractor directly.